



DRINKING WATER SYSTEM INSPECTION REPORT

Health Protection

SYSTEM NAME: Errington Elementary School E.H.O. NAME: Griffin Anthony
 ADDRESS: 1390 Fairdowne Road, Errington POSTAL CODE: _____ SYSTEM NUMBER: _____
 OPERATOR: School District 69 INSPECTION DATE (DMY): 25, 9, 13 TIME SPENT (Hrs. - nearest 1/4): _____

SYSTEM TYPE (CHECK One) Operations & Maintenance Manager: Dino Stielich TYPE OF INSPECTION
 > 20,000 (DWP) 10,001 - 20,000 (DWM) 301 - 10,000 (DWT) 15 - 300 (DWC) 2 - 14 (DWS)
 1 - SERVES PUBLIC (DWQ) 1 HAULER (DWH) INITIAL ROUTINE
 COMPLAINT FOLLOW-UP

CRITICAL HAZARD
 These items relate to Public Health Safety & MUST RECEIVE IMMEDIATE ATTENTION
Microbiological Contamination of Raw Water Supply Due to:
 301 Flood
 302 Sewage
 303 Industrial
 304 Agriculture
 305 Other (Specify) _____
 306 Chemical Contamination of Raw Water Supply
 307 Contamination of Finished Water - Reservoir
 308 Contamination of Finished Water - Mains
 309 Cross-Connection
 310 Use of Unapproved Source
 311 Interruption of Treatment
 312 Inadequate Treatment
 313 Other (Specify) _____

SANITATION & MAINTENANCE
 These items must be corrected within a designated time period
 314 Improper Maintenance of Distribution System
 315 Improper or No Disinfection of New or Repaired Main
 316 Source Unprotected and Subject to Contamination
 317 Inadequate or Improper Construction of Water Works
 318 Inadequate Microbiological Analysis Data
 319 Inadequate Chemical Analysis Data
 320 Interruption of Treatment
 321 Inadequate Treatment
 322 Emergency Response Plan
 323 Other (Specify) _____

CODE	FINDINGS AND ACTIONS REQUIRED
✓	Excellent record keeping for system maintenance and chlorine residuals.
✓	Good sampling history (12 of 12 required samples submitted).
✓	Good bacteriological results.
✓	Chlorine residual 1.18 ppm in reservoir during inspection; raw water audit sample collected.
322	Emergency Response Plan requires updating with current VIHA contact and SD69 contact information. Please provide our office with a copy of revised ERP.
323	Annual report for 2012 requires posting.
319	Chemical Water quality analysis required. Please forward lab results to our office by October 31, 2013.

NOTE: Due to elevated combined chlorine detected in reservoir, cleaning of reservoir will be undertaken before end of 2013

At the time of inspection this system has a hazard rating of HIGH MODERATE LOW Issue Permit Conditions of Permit

FOLLOW UP VISIT PHONE Date _____

RECEIVED BY: emailed and mailed to Dino Stielich PRINT NAME: Dino Stielich E.H.O.: Griffin

EMERGENCY RESPONSE PLANNING FOR SMALL WATERWORKS SYSTEMS

Sd69(Qualicum) Errington Elementary School
1390 Fairdowne Rd., Errington, BC

EMERGENCY RESPONSE PLAN CONTACT LIST

Personnel Contacts

	Phone	Emerg	Fax
Operator's Name: SD69(Qualicum)	250-248-2067	250-954-9304	250-954-3028
Staff Name: Earl Billingsley Operations & Maint Manager	250-248-2067	250-228-0276	250-954-3028
Doug DeVito Operations & Maint Chargehand	250-248-2067	250-954-9304	250-954-3028
Steve Halliday, School Principal	250-248-8446		250-954-1593

Emergency Contact Numbers

Medical Health Officer	<i>Dr. Hasselback</i> 250-248-2044	<i>250-755-6215</i>	<i>250-755-3372</i>
Environmental Health Officer	<i>Anthony Griffin</i> Bill Wrathall 250-248-2044	<i>250-755-6215</i>	<i>250-755-3372</i>
Public Health Engineer	<i>Murray Sexton</i> 250-248-2044	"	250-248-8624 "
Prov. Emerg. Preparedness Prog.			
Police	Parksville RCMP	250-248-6111	911
Ministry of Environment		250-751-3100	
Department of Fisheries		250-746-1210	
Hospital	Nanaimo Regional	250-248-2332	
Fire Department	Errington Volunteer	250-248-6601	911
BC Hydro		1-888-769-3766	
Pump Information #1	Gould 3.4 HP 2300 Submersible		
#2	Gould 7 1/2 HP 36505		
Chlorinator Information	LMI A741		
Bulk Water Hauler	Red Williams	250-248-5552	250-752-7017
Bottled Water Supplier	CDN Springs	1-800-665-3285	