

School District Information Health Authority (HA) Information

SD No	69	Region	Region 2 Central Island
SD Name	Qualicum	Contact Name	Claire Webb
SD Contact Name	Phil Munro	Contact Phone	250-947-8222 (extension 39185)
SD Contact Phone	250-954-3030	Report Submitted	Yes
Report Date	30-Mar-23	Report Submission	30-Mar-23

School Sampling Information

Ministry Asset Number	Facility Name	Year Facility Built	Total Number of Fixtures Identified	Number of Fixtures Sampled in this Report	Number of Fixtures Sampled in Last 3 years	Proportion of fixtures sampled this year Policy requires 33% fixtures to be sampled each year	Number of fixtures remaining to be sampled in this 3-year cycle.
120845	Errington Eler	1999	11	11	0	1	0
113685	Arrowview Ele	1999	9	9	0	1	0
110500	Nanoose Bay	1993	7	7	0	1	0
120752	Springwood E	1996	15	15	0	1	0
120970	Qualicum Bez	2003	8	8	0	1	0
120329	Oceanside El	1993	12	12	0	1	0

School Identifier	Testing information						Result		Mitigation Strategy Selected	Public Communication Plan
Ministry Asset Number	Test Date (dd-mm-yyyy)	Time of test (24hr clock)	Outlet ID (optional)	Sample Type	Fixture Type	Fixture Location Description	Lead Result (mg/L)	Exceeds Maximum Acceptable Concentration		
123456	11-12-2022	07:45:00	211_1_104_CF	Flushed	CF	Classroom Faucet (CF) in room 104, first floor, facility 211.	0.0043	No	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
120845	14-02-2023	06:20:00	EES 1A	First Draw	DW	Drinking fountain main entrance	0.00028	No	NA	FALSE
120845	14-02-2023	06:21:00	EES 1B	Flushed	DW	Drinking fountain main entrance	0.00063	No	NA	FALSE
120845	14-02-2023	06:24:00	EES 2A	First Draw	DW	Drinking fountain outside room 7	0.0007	No	NA	FALSE
120845	14-02-2023	06:25:00	EES 2B	Flushed	DW	Drinking fountain outside room 7	0.00043	No	NA	FALSE
120845	14-02-2023	06:27:00	EES 3A	First Draw	DW	Drinking fountain between rooms 14 & 16	0.0012	No	NA	FALSE
120845	14-02-2023	06:28:00	EES 3B	Flushed	DW	Drinking fountain between rooms 14 & 16	0.0005	No	NA	FALSE
120845	14-02-2023	06:30:00	EES 4A	First Draw	DW	Drinking fountain room 11	0.0012	No	NA	FALSE
120845	14-02-2023	06:31:00	EES 4B	Flushed	DW	Drinking fountain room 11	0.00079	No	NA	FALSE
120845	14-02-2023	06:36:00	EES 5A	First Draw	DW	Drinking fountain room 13	0.0016	No	NA	FALSE
120845	14-02-2023	06:37:00	EES 5B	Flushed	DW	Drinking fountain room 13	0.00042	No	NA	FALSE
120845	14-02-2023	06:40:00	EES 6A	First Draw	DW	Drinking fountain between rooms 01 & 03	0.0011	No	NA	FALSE
120845	14-02-2023	06:41:00	EES 6B	Flushed	DW	Drinking fountain between rooms 01 & 03	0.00046	No	NA	FALSE
120845	14-02-2023	06:45:00	EES 7A	First Draw	DW	Drinking fountain outside gym	0.00061	No	NA	FALSE
120845	14-02-2023	06:46:00	EES 7B	Flushed	DW	Drinking fountain outside gym	0.00029	No	NA	FALSE
120845	14-02-2023	06:50:00	EES 8A	First Draw	KC	Kitchen sink in room 124 between rooms 11 & 13	0.0054	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
120845	14-02-2023	06:51:00	EES 8B	Flushed	KC	Kitchen sink in room 124 between rooms 11 & 13	0.001	No	NA	FALSE
120845	14-02-2023	06:54:00	EES 9A	First Draw	KC	Kitchen sink in staff room	0.0036	No	NA	FALSE
120845	14-02-2023	06:55:00	EES 9B	Flushed	KC	Kitchen sink in staff room	0.00055	No	NA	FALSE
120845	14-02-2023	06:59:00	EES 10A	First Draw	KC	Kitchen sink in room 147	0.0042	No	NA	FALSE
120845	14-02-2023	07:00:00	EES 10B	Flushed	KC	Kitchen sink in room 147	0.00048	No	NA	FALSE
120845	14-02-2023	07:02:00	EES 11A	First Draw	BF	Lavatory in office medical room 112B	0.014	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
120845	14-02-2023	07:03:00	EES 11B	Flushed	BF	Lavatory in office medical room 112B	0.0008	No	NA	FALSE
113685	14-02-2023	07:39:00	AES 1A	First Draw	DW	Drinking fountain outside room 1	0.0023	No	NA	FALSE
113685	14-02-2023	07:40:00	AES 1B	Flushed	DW	Drinking fountain outside room 1	0.00098	No	NA	FALSE
113685	14-02-2023	07:31:00	AES 2A	First Draw	DW	Drinking fountain outside room 7	0.001	No	NA	FALSE
113685	14-02-2023	07:32:00	AES 2B	Flushed	DW	Drinking fountain outside room 7	0.00051	No	NA	FALSE
113685	14-02-2023	07:35:00	AES 3A	First Draw	DW	Drinking fountain outside gym	0.0013	No	NA	FALSE
113685	14-02-2023	07:38:00	AES 3B	Flushed	DW	Drinking fountain outside gym	0.0016	No	NA	FALSE
113685	14-02-2023	07:23:00	AES 4A	First Draw	BF	Bottle filling station main entrance	0.00078	No	NA	FALSE
113685	14-02-2023	07:25:00	AES 4B	Flushed	BF	Bottle filling station main entrance	0.00074	No	NA	FALSE
113685	14-02-2023	07:27:00	AES 5A	First Draw	DW	Drinking fountain between rooms 12 & 13	0.0014	No	NA	FALSE
113685	14-02-2023	07:29:00	AES 5B	Flushed	DW	Drinking fountain between rooms 12 & 13	0.00081	No	NA	FALSE
113685	14-02-2023	07:28:00	AES 6A	First Draw	KC	Kitchen sink in staff room	0.005	No	NA	FALSE
113685	14-02-2023	07:29:00	AES 6B	Flushed	KC	Kitchen sink in staff room	0.0014	No	NA	FALSE
113685	14-02-2023	07:36:00	AES 7A	First Draw	KC	Kitchen sink between in room 124 rooms 6 & 8	0.012	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
113685	14-02-2023	07:37:00	AES 7B	Flushed	KC	Kitchen sink between in room 124 rooms 6 & 8	0.0014	No	NA	FALSE
113685	14-02-2023	07:31:00	AES 8A	First Draw	KC	Kitchen sink in gym area kitchen room 147	0.0037	No	NA	FALSE

113685	14-02-2023	07:34:00	AES 8B	Flushed	KC	Kitchen sink in gym area kitchen room 147	0.001	No	NA	FALSE
113685	14-02-2023	07:25:00	AES 9A	First Draw	BF	Lavatory in office medical room	0.0092	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
113685	14-02-2023	07:26:00	AES 9B	Flushed	BF	Lavatory in office medical room	0.00093	No	NA	FALSE
110500	13-02-2023	06:52:00	NBES 1A	First Draw	DW	Drinking fountain outside study 2 room	0.0002	No	NA	FALSE
110500	13-02-2023	06:54:00	NBES 1B	Flushed	DW	Drinking fountain outside study 2 room	0.0002	No	NA	FALSE
110500	13-02-2023	07:12:00	NBES 2A	First Draw	DW	Drinking fountain outside staff room	0.00025	No	NA	FALSE
110500	13-02-2023	07:14:00	NBES 2B	Flushed	DW	Drinking fountain outside staff room	0.0002	No	NA	FALSE
110500	13-02-2023	07:24:00	NBES 3A	First Draw	DW	Drinking fountain outside gym	0.0002	No	NA	FALSE
110500	13-02-2023	07:27:00	NBES 3B	Flushed	DW	Drinking fountain outside gym	0.00028	No	NA	FALSE
110500	13-02-2023	07:06:00	NBES 4A	First Draw	KC	Kitchen sink in medical room	0.00023	No	NA	FALSE
110500	13-02-2023	07:08:00	NBES 4B	Flushed	KC	Kitchen sink in medical room	0.0002	No	NA	FALSE
110500	13-02-2023	07:16:00	NBES 5A	First Draw	KC	Kitchen sink in staff room	0.0002	No	NA	FALSE
110500	13-02-2023	07:18:00	NBES 5B	Flushed	KC	Kitchen sink in staff room	0.0002	No	NA	FALSE
110500	13-02-2023	07:28:00	NBES 6A	First Draw	KC	Kitchen sink in kitchen 1 off gym	0.0002	No	NA	FALSE
110500	13-02-2023	07:30:00	NBES 6B	Flushed	KC	Kitchen sink in kitchen 1 off gym	0.0002	No	NA	FALSE
110500	13-02-2023	06:49:00	NBES 7A	First Draw	KC	Kitchen sink in kitchen 2 by room 9	0.0002	No	NA	FALSE
110500	13-02-2023	06:51:00	NBES 7B	Flushed	KC	Kitchen sink in kitchen 2 by room 9	0.0002	No	NA	FALSE
120752	10/2/2023	06:25:00	SES 1A	First Draw	DW	Drinking fountain outside room 118 washroom	0.00062	No	NA	FALSE
120752	10/2/2023	06:26:00	SES 1B	Flushed	DW	Drinking fountain outside room 118 washroom	0.0008	No	NA	FALSE
120752	10/2/2023	06:27:00	SES 2A	First Draw	DW	Drinking fountain between room 119/120 washroom	0.00064	No	NA	FALSE
120752	10/2/2023	06:28:00	SES 2B	Flushed	DW	Drinking fountain between room 119/120 washroom	0.00096	No	NA	FALSE
120752	10/2/2023	06:30:00	SES 3A	First Draw	DW	Drinking fountain outside band room 106B	0.0022	No	NA	FALSE
120752	10/2/2023	06:31:00	SES 3B	Flushed	DW	Drinking fountain outside band room 106B	0.00044	No	NA	FALSE
120752	10/2/2023	07:12:00	SES 6A	First Draw	DW	Drinking fountain outside room 218 washroom	0.0013	No	NA	FALSE
120752	10/2/2023	07:13:00	SES 6B	Flushed	DW	Drinking fountain outside room 218 washroom	0.002	No	NA	FALSE
120752	10/2/2023	06:40:00	SES 7A	First Draw	KC	Kitchen sink in staff room 123	0.0039	No	NA	FALSE
120752	10/2/2023	06:41:00	SES 7B	Flushed	KC	Kitchen sink in staff room 123	0.00093	No	NA	FALSE
120752	10/2/2023	06:42:00	SES 8A	First Draw	KC	Kitchen sink in life skills room 113	0.0015	No	NA	FALSE
120752	10/2/2023	06:43:00	SES 8B	Flushed	KC	Kitchen sink in life skills room 113	0.00033	No	NA	FALSE
120752	10/2/2023	06:46:00	SES 9A	First Draw	KC	Kitchen sink in kitchen 107B	0.0056	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
120752	10/2/2023	06:47:00	SES 9B	Flushed	KC	Kitchen sink in kitchen 107B	0.00062	No	NA	FALSE
120752	10/2/2023	06:53:00	SES 10A	First Draw	KC	Kitchen sink in office medical room 132	0.0046	No	NA	FALSE
120752	10/2/2023	06:54:00	SES 10B	Flushed	KC	Kitchen sink in office medical room 132	0.00058	No	NA	FALSE
120752	10/2/2023	06:56:00	SES 11A	First Draw	KC	Kitchen sink in foods room 106C station 1	0.0038	No	NA	FALSE
120752	10/2/2023	06:57:00	SES 11B	Flushed	KC	Kitchen sink in foods room 106C station 1	0.0006	No	NA	FALSE
120752	10/2/2023	06:58:00	SES 12A	First Draw	KC	Kitchen sink in foods room 106C station 2	0.0037	No	NA	FALSE
120752	10/2/2023	06:59:00	SES 12B	Flushed	KC	Kitchen sink in foods room 106C station 2	0.00049	No	NA	FALSE
120752	10/2/2023	07:00:00	SES 13A	First Draw	KC	Kitchen sink in foods room 106C station 3	0.0037	No	NA	FALSE
120752	10/2/2023	07:01:00	SES 13B	Flushed	KC	Kitchen sink in foods room 106C station 3	0.00056	No	NA	FALSE
120752	10/2/2023	07:02:00	SES 14A	First Draw	KC	Kitchen sink in foods room 106C station 4	0.0032	No	NA	FALSE
120752	10/2/2023	07:03:00	SES 14B	Flushed	KC	Kitchen sink in foods room 106C station 4	0.00087	No	NA	FALSE
120752	10/2/2023	07:04:00	SES 15A	First Draw	KC	Kitchen sink in foods room 106C station 5	0.0039	No	NA	FALSE
120752	10/2/2023	07:05:00	SES 15B	Flushed	KC	Kitchen sink in foods room 106C station 5	0.00082	No	NA	FALSE
120752	10/2/2023	07:06:00	SES 16A	First Draw	KC	Kitchen sink in foods room 106C station 6	0.00069	No	NA	FALSE
120752	10/2/2023	07:07:00	SES 16B	Flushed	KC	Kitchen sink in foods room 106C station 6	0.00058	No	NA	FALSE
120752	10/2/2023	07:08:00	SES 17A	First Draw	KC	Kitchen sink in foods room 106C station 7	0.00051	No	NA	FALSE
120752	10/2/2023	07:09:00	SES 17B	Flushed	KC	Kitchen sink in foods room 106C station 7	0.00047	No	NA	FALSE
120970	9/2/2023	06:28:00	QBES 1A	First Draw	DW	Drinking fountain outside staff room	0.001	No	NA	FALSE
120970	9/2/2023	06:29:00	QBES 1B	Flushed	DW	Drinking fountain outside staff room	0.0011	No	NA	FALSE
120970	9/2/2023	06:30:00	QBES 2A	First Draw	DW	Drinking fountain outside room 132	0.0041	No	NA	FALSE
120970	9/2/2023	06:31:00	QBES 2B	Flushed	DW	Drinking fountain outside room 132	0.0011	No	NA	FALSE
120970	9/2/2023	06:44:00	QBES 3A	First Draw	BF	Bottle filler outside room 214	0.00062	No	NA	FALSE
120970	9/2/2023	06:45:00	QBES 3B	Flushed	BF	Bottle filler outside room 214	0.00086	No	NA	FALSE
120970	9/2/2023	06:32:00	QBES 4A	First Draw	KC	Kitchen sink in staff room	0.002	No	NA	FALSE
120970	9/2/2023	06:33:00	QBES 4B	Flushed	KC	Kitchen sink in staff room	0.0022	No	NA	FALSE
120970	9/2/2023	06:38:00	QBES 5A	First Draw	KC	Kitchen sink in room 118 kitchen	0.0024	No	NA	FALSE
120970	9/2/2023	06:39:00	QBES 5B	Flushed	KC	Kitchen sink in room 118 kitchen	0.0025	No	NA	FALSE
120970	9/2/2023	06:42:00	QBES 6A	First Draw	KC	Kitchen sink in room 140	0.0039	No	NA	FALSE
120970	9/2/2023	06:43:00	QBES 6B	Flushed	KC	Kitchen sink in room 140	0.0017	No	NA	FALSE
120970	9/2/2023	06:47:00	QBES 7A	First Draw	LF	Lab sink in room 211	0.02	Yes	4F	Install a NSF 53/42 certified filter if the water point is essential and the source of lead is difficult to replace or could not be located and corrected. Retest after corrective work. Inform management, regional public health office, and water supplier. Exceedance in flushed sample may indicate corrosive water or presence of upstream lead plumbing. Investigate other outlets in the facility for lead. Expert advice in conducting investigation recommended.

120970	9/2/2023	06:48:00	QBES 7B	Flushed	LF	Lab sink in room 211	0.012	Yes	4F
120970	9/2/2023	06:40:00	QBES 8A	First Draw	BF	Lavatory in office medical room 141	0.0041	No	NA
120970	9/2/2023	06:41:00	QBES 8B	Flushed	BF	Lavatory in office medical room 141	0.0012	No	NA
120329	14/2/2023	07:10:00	OES 1A	First Draw	BF	Bottle filler between room 115 & 116 WR	0.00099	No	NA
120329	14/2/2023	07:12:00	OES 1B	Flushed	BF	Bottle filler between room 115 & 116 WR	0.00027	No	NA
120329	14/2/2023	06:40:00	OES 5A	First Draw	DW	Drinking fountain outside music room 119	0.00073	No	NA
120329	14/2/2023	06:42:00	OES 5B	Flushed	DW	Drinking fountain outside music room 119	0.00096	No	NA
120329	14/2/2023	06:27:00	OES 6A	First Draw	KC	Kitchen sink in room 108 kitchen	0.00062	No	NA
120329	14/2/2023	06:29:00	OES 6B	Flushed	KC	Kitchen sink in room 108 kitchen	0.0003	No	NA
120329	14/2/2023	06:19:00	OES 7A	First Draw	KC	Kitchen sink in staff room	0.0026	No	NA
120329	14/2/2023	06:21:00	OES 7B	Flushed	KC	Kitchen sink in staff room	0.00031	No	NA
120329	14/2/2023	06:33:00	OES 8A	First Draw	KC	Kitchen sink in room 118 multi purpose room kitchen	0.0016	No	NA
120329	14/2/2023	06:35:00	OES 8B	Flushed	KC	Kitchen sink in room 118 multi purpose room kitchen	0.00066	No	NA
120329	14/2/2023	06:46:00	OES 9A	First Draw	KC	Kitchen sink in home ec/teachers station	0.0024	No	NA
120329	14/2/2023	06:48:00	OES 9B	Flushed	KC	Kitchen sink in home ec/teachers station	0.0024	No	NA
120329	14/2/2023	07:06:00	OES 10A	First Draw	KC	Kitchen sink in home ec/station 1	0.0047	No	NA
120329	14/2/2023	07:08:00	OES 10B	Flushed	KC	Kitchen sink in home ec/station 1	0.00065	No	NA
120329	14/2/2023	07:03:00	OES 11A	First Draw	KC	Kitchen sink in home ec/station 2	0.035	Yes	2A
120329	14/2/2023	07:05:00	OES 11B	Flushed	KC	Kitchen sink in home ec/station 2	0.0013	No	NA
120329	14/2/2023	06:58:00	OES 12A	First Draw	KC	Kitchen sink in home ec/station 3	0.0018	No	NA
120329	14/2/2023	07:01:00	OES 12B	Flushed	KC	Kitchen sink in home ec/station 3	0.0009	No	NA
120329	14/2/2023	06:55:00	OES 13A	First Draw	KC	Kitchen sink in home ec/station 4	0.0014	No	NA
120329	14/2/2023	06:57:00	OES 13B	Flushed	KC	Kitchen sink in home ec/station 4	0.00065	No	NA
120329	14/2/2023	06:52:00	OES 14A	First Draw	KC	Kitchen sink in home ec/station 5	0.0015	No	NA
120329	14/2/2023	06:54:00	OES 14B	Flushed	KC	Kitchen sink in home ec/station 5	0.00082	No	NA
120329	14/2/2023	06:49:00	OES 15A	First Draw	KC	Kitchen sink in home ec/station 6	0.0031	No	NA
120329	14/2/2023	06:51:00	OES 15B	Flushed	KC	Kitchen sink in home ec/station 6	0.0014	No	NA

Install a NSF 53/42 certified filter if the water point is essential and the source of lead is difficult to replace or could not be located and corrected. Retest after corrective work. Inform management, regional public health office, and water supplier. Exceedance in flushed sample may indicate corrosive water or presence of upstream lead plumbing. Investigate other outlets in the facility for lead. Expert advice in conducting investigation recommended.

Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.